

**\$16,000**

Inspection Number: 2723194

Inspection Type: Trade

Sub-Type:

Created By: Heydenreich, David W.

Created Date: 05/07/21 10:43:57

Salesperson: Swank, Les W.

Inspector: Heydenreich, David W.

Client Name:

Client Company: City of Tontitown

Serial Number: 031051369

Product Family: BACKHOE LOADER

Manufacturer: NEW HOLLAND LTD.

Model: LB110B

Stock Number:

Year: 2005

SMU / Hours: 3,240

Location: Tontitown, AR, United States

Asking Price:

Repair Charges Subtotal:

Cleaning: 250

Painting:

Freight:

Total Custom Charges: 660

Other Charges Subtotal: 910

Manager's Adjustment Charge:

Total Cost: 16,910

Total Charges: 910

**Assigned Trade Value: 16,000 USD**

Notes: ATV \$16K, USEFAIR, engine compartment taped shut, repair AC, replace front glass, leaking steering cylinder, Leaking swing cylinders, 4x4 does not work. Offer good thru 6/13/2021  
TJT

**Les Swank**

Premier Account Manager

Office +1 (479) 927-8965

Mobile +1 (479) 225-1329

